


## **NEWHALL FOUNDATION EVALUATION PROJECT**







## Newhall Foundation Evaluation Project Status of Completed Condition Assessments

This table provides Haley & Aldrich's initial conclusion of whether or not the property's conditions are impacted by waste fill and/or remediation based on our observations of the property. If foundation and/or water issues were observed, the nature of the issues, and any recommended repairs to address them, will be addressed in individual property reports following investigation to verify our observations and engineering evaluations of the issues. Owners of properties shown below were informed of this initial conclusion by mail as of April 2, 2025.

Address of Property of Condition Assessment Completed through 3/31/2025	Property Possibly Impacted by Waste Fill and/or Remediation	Category of Issue Observed (S=Structural, W=Water)
327 AUGUR ST	Yes	S, W
342 AUGUR ST	Yes	S
90 BRYDEN TR	Yes	S, W
99 BRYDEN TR	Yes	W
112 BRYDEN TR	Yes	S, W
117 BRYDEN TR	Yes	S, W
125 BRYDEN TR	Yes	S, W
229 BUTLER ST	Yes	S, W
231 BUTLER ST	Yes	S, W
234 BUTLER ST	Yes	S, W
238 BUTLER ST	Yes	S, W
25 EDWARDS ST	Yes	S, W
29 EDWARDS ST	Yes	S, W
49 EDWARDS ST	Yes	S
155 GOODRICH ST	No	
211 GOODRICH ST	No	
257 GOODRICH ST	Yes	S, W
265 GOODRICH ST	Yes	W
17 HARRIS ST	Yes	W
25 MARLBORO ST	No	
34 MARLBORO ST	Yes	S, W
69 MARLBORO ST	No	
87 MARLBORO ST	Yes	W
115 MARLBORO ST	Yes	W

## Newhall Foundation Evaluation Project Status of Completed Condition Assessments

Address of Property of Condition Assessment Completed through 3/31/2025	Property Possibly Impacted by Waste Fill and/or Remediation	Category of Issue Observed (S=Structural, W=Water)
92 MORSE ST	Yes	W
102 MORSE ST	No	
103 MORSE ST	Yes	W
108 MORSE ST	No	
109 MORSE ST	Yes	S, W
115 MORSE ST	Yes	S, W
121 MORSE ST	Yes	S, W
127 MORSE ST	Yes	S, W
135 MORSE ST	Yes	S, W
161 MORSE ST	No	
165 MORSE ST	Yes	S
172 MORSE ST	No	
176 MORSE ST	Yes	W
180 MORSE ST	Yes	W
222 MORSE ST	Yes	W
259 MORSE ST	Yes	W
267 MORSE ST	Yes	W
283 MORSE ST	Yes	S, W
299 MORSE ST	No	
18 NEWBURY ST	Yes	W
22 NEWBURY ST	Yes	W
26 NEWBURY ST	Yes	W
468 NEWHALL ST	Yes	S, W
474 NEWHALL ST	Yes	S, W
477 NEWHALL ST	Yes	W
626 NEWHALL ST	No	
650 NEWHALL ST	No	
678 NEWHALL ST	No	
10 NORTH SHEFFIELD ST	No	
32 NORTH SHEFFIELD ST	No	
56 NORTH SHEFFIELD ST	No	

## Newhall Foundation Evaluation Project Status of Completed Condition Assessments

Address of Property of Condition Assessment Completed through 3/31/2025	Property Possibly Impacted by Waste Fill and/or Remediation	Category of Issue Observed (S=Structural, W=Water)
14 PROSPECT LA	No	
457 SHELTON AVE	Yes	W
492-494 SHELTON AVE	Yes	S, W
502 SHELTON AVE	Yes	S, W
509 SHELTON AVE	No	
163 SHEPARD ST	Yes	W
17 ST MARY ST	Yes	W
27 ST MARY ST	Yes	W
39 ST MARY ST	Yes	S, W
45 ST MARY ST	Yes	S, W
46 WADSWORTH ST	Yes	S
54 WADSWORTH ST	Yes	W
962 WINCHESTER AVE	No	
985 WINCHESTER AVE	Yes	W
1002 WINCHESTER AVE	No	
1027 WINCHESTER AVE	Yes	S, W
1032 WINCHESTER AVE	No	
403-405 NEWHALL ST	Yes	S, W
390 GOODRICH ST	Yes	S, W